

# LASER cutting

If you are not getting a good cut from your laser, you may be experiencing any of the following:

## Troubleshooting checklist

Check and correct	Time required (mins)
A Nozzle contamination	1-2
B Laser power and pulsing conditions	1-5
C Cutting speed	1-2
D Cutting gas	1-2
E Nozzle-material standoff	1-2
F Nozzle type, condition and alignment	1-10
G Material specification and condition	1-5
H Lens type, condition and alignment	10-20
I Beam steering mirror condition and alignment	5-60 per mirror
J Laser mode quality and polarisation	20-40

### A. Nozzle contamination

Dirt or spatter on the nozzle may deflect the gas jet to one side  
→ Wipe the nozzle or replace if damaged

### B. Laser power and pulsing conditions

- Compare laser power and pulse settings to those used successfully on similar jobs
  - If power level is lower than usual:
    - The laser may need time to warm up (up to 30 mins)
    - The helium supply is running low
    - The laser needs tuning
    - The laser needs servicing
- E.g. internal mirrors need to be cleaned  
Requires trained personnel

### C. Cutting speed

Compare cutting speed to those used successfully on similar jobs  
→ Try increasing and decreasing the speed by 10% and 20%

### D. Cutting gas


- Check the type of gas being used against similar successful jobs
- Check supply pressure and flow
  - Nozzle blockages will affect pressure and flow
  - It is best to have both a flow meter and a pressure gauge
  - Excessive oxygen pressure results in burning of corners and loss of fine details
- Insufficient gas purity or gas supply contamination
  - Contact your gas supplier
  - Oxygen cutting: cutting speed reduced
  - Nitrogen cutting: surface quality reduced

### E. Nozzle-material standoff

Compare to earlier successful results  
→ Normally the standoff is 0.25-2 mm  
→ Changing non-identical nozzles may change standoff  
Alter nozzle-lens distance to reoptimise process

### F. Nozzle type, condition and alignment

- Is the nozzle of the right type (exit diameter) for the job?
  - Is the nozzle worn or scratched?
  - Is the laser in the centre of the nozzle (i.e. centre of the gas jet)?
- If not:
- The machine will not cut equally well in all directions
  - Sparks may exit top of the cut zone when cutting in certain directions
  - Reduction of sparks leaving the bottom of the cut when cutting in certain directions



### G. Material specification and condition

- What is the material?
- Is the condition of the material affecting the cutting?
  - Surface coating (rust, paint, mill scale, etc.)
  - Deep scratches

### H. Lens type, condition and alignment


- Is the right focal length lens being used? Is it fitted correctly?
- Is the lens scratched or dirty? Both can give cutting problems  
Even if it is clean it may have become over-heated
- Is the laser beam correctly aligned onto the lens?  
→ Beam steering mirrors may need realignment

### I. Beam steering mirror condition and alignment

- Are the mirrors clean?
    - Take power readings after each one
  - Alignment should be square and central
    - Realignment of mirrors requires training
- Power losses should be below 5% per mirror


### J. Laser mode quality and polarisation

- The distribution of energy across the laser beam cross section is called its mode
  - Poor mode quality results in poor cutting quality
  - Laser mode identification and tuning require training




- CO<sub>2</sub> laser beam polarisation requires careful control for successful metal cutting
  - If circular profiles are oval on the bottom but circular on top, the polarising mirror(s) may need cleaning or replacing

### Gas consumption vs. nozzle size



## Correct conditions

### Good cut




This shows a good cut in 8 mm mild steel. Smooth, square cut edge with a light scale of oxide.

### Material-related fault



Example of how material quality can affect cut quality - oxygen cutting of low-grade mild steel.

### Material-related fault



- Oxidation of the cut is evident at 100 ppm purity.  
- The edge becomes rough at 0.1 % purity (1000 ppm).


## Common faults

### Dross



Effect	Problem	Action
Dross (oxygen & nitrogen cutting)	Insufficient melt clearance	Reduce speed
	Processing too fast - evidence of curved drag lines	Reduce speed
	Low pressure - evidence of curved drag lines	Increase gas pressure
	Low power	Increase power
	Poor focus	Check lens
	Nozzle too narrow	Increase nozzle diameter

### Slide burning



Effect	Problem	Action
Side burning (oxygen cutting)	Oxygen pressure too high	Reduce gas pressure
	Processing too slowly	Increase speed
	Damaged nozzle	Check/replace nozzle

### Cutting unequal in x-y plane

Effect	Problem	Action
Cutting unequal in x-y plane	Polarisation problems	Check and replace
	Damaged phase retarder	Check and replace
	Beam off centre	Align to nozzle

## Acknowledgements

Dr John Powell - LIA Guide to Laser Cutting  
(Pub: Laser Institute of America)